

PAINT TYPE Solvent-based urethane alkyd paint for interior and exterior floors. It produces a gloss surface that is easy to keep clean.

USAGE Suitable for new and previously with alkyd paints painted floors of e.g. concrete, wood, cork, carpet and brick, when the surfaces are affected by normal household strains.
It is recommended that TEKNOFLOOR 2K Concrete Paint is used when painting floors that will be subjected to strong action by water or chemicals, or to heavy abrasion.

TECHNICAL DATA

Solids About 50 % by volume

Practical spreading rate 6 - 10 m²/l depending on the absorbency of the surface

Density Abt. 1.2 g/ml

Drying time, +23°C

- dust free after 1 hour
- fit for light traffic after 10 hours
- overcoatable The following day

Thinner, clean up TEKNOSOLV 1621

Finish Gloss

Colours Standard colours according to the TEKNOFLOOR Colour Card.
The paint is included in the Teknomix tinting system.

SAFETY MARKINGS

See Material Safety Data Sheet.

NOTE! Because of the danger of self-ignition, any waste from the product, spray mist and soiled rags etc. are to be kept in a fire-proof place in air-tight containers, alternatively the waste is to be burned. Immersion in water is also recommended. (See Material Safety Data Sheet, paragraph 7.1.)

PTO

DIRECTION FOR USE**Surface preparation and application**

UNCOATED CONCRETE FLOORS are to be at least one month old. Clean the surfaces from dense laitance by etching with BETONI-PEITTAUSLIUOS Etching liquid and allow the surfaces to dry. Brittle and powdery surfaces must always be sanded. Remove oil and grease with TEKNOSOLV 1621. Brush the floor or clean with vacuum-cleaner to remove the dust. Prime the surface with paint diluted by 20% with TEKNOSOLV 1621 and finish with one coat of undiluted paint.

UNCOATED WOODEN FLOORS: Clean the floors from grease, dirt and dust. Fill dents and cracks with SILORA A Carpentry Filler. Prime with paint diluted by 10% with TEKNOSOLV 1621 and finish with one coat of undiluted paint.

PREVIOUSLY PAINTED FLOORS: Scrape or sand off all loose paint. Matt down old paint coats by sanding. Clean the surfaces from grease, dirt and dust. Prime bare spots with diluted paint and finish with a full coat of undiluted paint.

Remove all floor polishes before painting cork flooring or similar floors.

Before use stir the paint thoroughly.
Apply by brush or roller.

Application conditions

The surface to be painted must be dry. During the application and drying period the temperature of the ambient air, the surface and the paint shall be above +10°C and the relative air humidity below 80%.

Care instructions

The painted surface reaches its final hardness and washability within 3 - 4 weeks. Rough handling and washing is to be avoided during this period. Stained surfaces can be cleaned with a moist cleaning cloth or mop. Use a neutral detergent. Very dirty surfaces can later be cleaned with a slightly alkaline universal washing detergent.

The information of this data sheet is based on laboratory tests and practical experience. The figures are for guidance only and depend on, for example, colour and gloss. As we have no control over the use and application conditions, we are only responsible for the quality of the product and guarantee that it conforms to our quality control. We accept no liability for any loss or damage resulting from the application of the product contrary to the directions or the intended use. The latest versions of our data sheets, material safety data sheets and system sheets are on our home pages www.teknos.com.
